



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program June 7, 2010

Reviewed: 

Mine Name: CMC ROCK Point South	Permit Number: S/035/0041
Operator Name: CMC ROCK LLC	Inspection Date: April 22, 2010
Inspector(s): L Heppler	Time: 7:30 am
Other Participants: none	Mine Status :Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>


Bond Renewal Date: 09-08-2014 **Bond Amount:** \$25,200 **Permit fee** is up to date

Purpose of Inspection: Routine annual Inspection. This site was inspected as a small mine site on 10/27/2009

Inspection Summary: This site is accessed through a locked gate, but there is other entrances that can access the site. Erosion is evident at the site. All deleterious materials were properly stored. Topsoil was stockpiled at the upper edge of the excavation. No revegetation has been done. Photos were taken to document site conditions.

Conclusions and Recommendations: The Operator needs to put more effort into erosion control. This site appears to be operated by one Operator yet there is 2 permits for this site. The Operator either needs to do a large mine permit for 10 acres or Transfer the existing mine permit into the Operators name. Operator has 30 days to comply with all local, state and federal rules. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature



LAH:vs

cc: Martin White

O:\M035-SaltLake\S0350041-CMCRockPointSouth\inspections\Insp-04222010.doc



